

EXCESSIVE FLASHING REDUCTION ON PLAD SINGLE-DIE/ BI-RECTIONAL DEVICES THRU STACK HEIGHT ANALYSIS

Jason G. Sison
Primitivo L. Regencia Jr.

Process Engineering - EOL
Fastech Advance Assembly Inc,
Ampere Street cor. West Road Ligth Industry and Science Park 1
Cabuyao, Laguna, Philippines 4025
jgsison@fastech.com.ph, jrabella@fastech.com.ph, jlregencia@fastech.com.ph

ABSTRACT

PLAD or Plastic Large Area Device are surface mount package devices with typical applications in lightning and automotive load dump protection. The PLAD package combines a large die size with a large exposed bottom-side metal slug for heat sinking that improves power handling as compared to through-hole package designs.

Molding process encapsulates the die-moly-metal slug assembly using molding compound in such a way that the resulting composite materials are robustly protected and functions to its intended purpose as shown in Fig 1. However, due to process and equipment variations, product yield is affected. Defects such as mold flashing and package chip-out are the top defects affecting this package. Such defects resulted to yield loss, production cost loss and customer concerns.




Fig 1: PLAD device parts

Re-engineering and modification of leadframe bend in PLAD15KPCA devices results in significant improvements in terms of productivity, costs and quality. This is expounded into a detailed information on the following sections of this paper.

1.0 INTRODUCTION

Four assembly types comprises PLAD package family. As shown on Fig 2, these package configuration are:

- A. Dual-die/ bi-directional devices
- B. Dual-die/ uni- directional devices
- C. Single-die/ bi-directional devices
- D. Single-die/ uni-directional devices




Fig 3: PLAD Product configuration

Each package type has different response in terms of flashing when encapsulated. Single-die assembly tends to have severe/ excessive flashing on heatsink side of the package. Flashing or mold flash are excess plastic material to a molded product which must usually be removed. In PLAD process, manual deflash is performed; manual deflash is typically conducted using hand deflashing tool, sand paper, eraser or equivalent.

1.1 Problem description:

Inherent mold flashing on heatsink area (as shown on Fig 3) of single-die/ bi-directional or 15KPCA devices of PLAD package causes low UPH on deflashing process. Such heavy flashing induce process difficulty and prolonged cycle time on manual deflash. Aside from this low UPH, defect ppm is also affected due to package chip-out rejections caused by this excessive flashing on heatsink.




Fig 3: Heatsink flashing signature of PLAD15KPCA

Based on PLAD UPH matrix for Manual Deflash process, there was additional process cost of \$4.2K for lots with 87.7% flashing defect rate.

PACKAGE	DESCRIPTION	UPH	PROCESS COST PER UNIT	VOLUME 2022	COST PER PROCESS	ADDITIONAL COST	UPH LOSS
PLAD-15KP	ORIGINAL	186	\$0.0189	160,000	\$3,027.96	\$4,192.55	58.06%
	BK DIE - 87.7% FLASHING	78	\$0.0451		\$7,220.51		

Fig 4: UPH Matrix for Manual Deflash

As shown on funnel/ bottleneck process chart, Manual deflash process UPH was further reduced from 186 UPH to 78 UPH or reduction of 58.06% due to excessive flashing on 15KPCA devices.




Fig 5: Manual Deflash UPH without flashing




Fig 6: Manual Deflash UPH with flashing

PPM rejection rate for package chip-out (2.84 KPPM) also increased due to difficulty in removing the thick flashing manually.




Fig 7: PPM Trend of Package Chip-out for 15KPCA

3.0 METHODOLOGY

- Use fish bone diagram for rootcause analysis.
- Analyze and validate potential causes of defects.
- Qualified and gather all needed data and institute improvements.
- Perform identified actionables and gather results.
- Perform the final qualification and documentations
- Utilize by production and monitor effectiveness.

3.1 Failure Analysis:

Fishbone Analysis for Excessive Flashing.




Figure 8: Fishbone Analysis of Excessive Flashing on 15KPCA

3.2.1 Validation

1. Material

- Tilted/ depressed heatsink
- Low/ High assembly stacked height

Based on current molded units, it was observed that the heavy flashing is evident on leadside of the strips. Further measurement and failure analysis showed the

heatsink is tilted on lead side and not planar with respect to the plastic mold of the units.




Fig 9: Heavy mold flashing on lead side of the molded strips



Tilted/Depressed Heatsink				
Unit #	Q1	Q2	Q3	Q4
1	+0.010	-0.082	-0.043	+0.028
2	+0.028	-0.080	-0.040	+0.026
3	+0.012	-0.073	-0.020	+0.033



Planar Heatsink - VZ POS Ref				
Unit #	Q1	Q2	Q3	Q4
A	+0.026	+0.003	+0.008	+0.025
B	+0.024	+0.002	+0.004	+0.022

As shown on heatsink surface measurement, sides Q2 and Q3 on affected units have depression of 0.020 to 0.082mm whereas the units with no flashing have no indications of depressed heatsink. Cross-section showed unplanar heatsink, see Fig 10.






Fig 10: Cross-section of units with flashing on heatsink

Units without flashing on heatsink have evident planar heatsink with respect to the plastic mold perimeters shown of Fig 11.




Fig 11: Cross-section of units without flashing on heatsink

- Assembly Internal Component Stack Height Analysis

Cross-section analysis was conducted in order to compare assembly stacked height of good units and affected units. Based on layer measurement of the assembly as shown in Fig 12, it was noted that the units without flashing have low lead bend, 6.85mils, compared to the standard lead bend which is 9-10 mils.

STACK HEIGHT COMPARISON					
NO HEAT SINK FLASHING					
WITH HEAT SINK FLASHING					
Sample #1					
COMPONENT HEIGHT COMPARISON (in inch)					
HEIGHT CODE	NO HEAT SINK FLASHING	WITH HEAT SINK FLASHING	DELTA	NO HEAT SINK FLASHING	WITH HEAT SINK FLASHING
A (heatsink)	0.0020	0.0020	0.0000	0.0020	0.0020
B (board)	0.0030	0.0030	0.0000	0.0030	0.0030
C (lead)	0.0085	0.0085	0.0000	0.0085	0.0085
D (board)	0.0085	0.0085	0.0000	0.0085	0.0085
E (silicon die)	0.0120	0.0120	0.0000	0.0120	0.0120
F (board)	0.0075	0.0075	0.0000	0.0075	0.0075
G (lead)	0.0085	0.0085	0.0000	0.0085	0.0085
H (board)	0.0075	0.0075	0.0000	0.0075	0.0075
I (leadframe)	0.0020	0.0020	0.0000	0.0020	0.0020
J (lead frame height)	N/A	N/A	-	0.0020	0.0020
K (bending height)	N/A	N/A	-	0.0085	0.0085
Total height (A to J)	0.0879	0.0884	0.0005	0.0879	0.0884

Fig 12: Assembly Stack height

Further validation on another set of samples showed lead bend height of 6.15mils on samples without flashing.




Fig 13: Assembly Stack height

No Heatsink Flashing as shown in Fig 14:

- Two (2) units samples of units with NO FLASHING on heatsink showed the depressed area of lead bending adjacent to moly. It is an indication of lead bending height is below the minimum that potentially contributed by bending tool variation.
- Based on data, low bending height can eliminate the flashing on heatsink as it reached and touching the top mold surface.
- Bending height of with and without flashing showed the 2.5 mils and 3.2 mils delta




Fig 14: No HS flashing with pressing down of lead bend

WITH Heatsink Flashing as shown in Fig 15:

- No abnormality noted on internal component stuck height measurement.
- No abnormality noted on lead bending and all passed the requirements. (No depressed lead bending)
- Bending height within the requirements do not touch the top mold surface thus creating the heavy flashing on heatsink.




Fig 15: With HS flashing with pressing down of lead bend

Old Samples With No HS Flashing – Datecode 1946

Component cross-section on Fig 16:

- Both samples showed slight pressing down on bending area (delta of 2.2 and 1.85 mils).
- Gap between leadframe and moly




Fig 16: Old samples with No HS flashing

Component Cross-section on Fig 17:

- 2/2 samples with NO FLASHING on heatsink showed similar depressed area of lead bending adjacent to moly.
- Depressed area of lead bending for both sample is 2.2 mils and 1.85 mils.
- Bending height of 5.65 – 6.0 mils on both samples with No HS Flashing (Specs: 9- 11 mils)
- Gap on between leadframe and moly on Leadframeside due to depressed area of leadbend.





Fig 17: Old samples with No HS flashing

3.3 Experimental Section

3.3.1 Objective

- To identify and analyze the causes of excessive flashing on heatsink.
- To improve the UPH in Manual Deflash process of PLAD for 15KPCA.



3.3.2 Equipment and Materials

- Bending Press and tool
- Mold chase
- Mold press
- PLAD strips (bend/ unbended)
- Epoxy Molding compound
- Plasma machine
- Argon gas
- CDA Box
- C-SAM machine
- Profile Projector

Lead Bending Data for 8.5mils bend height

Strap #	Bend Height (mils)			
	Unit 1	Unit 2	Unit 3	Unit 4
1	8.5	8.7	8.6	8.7
2	8.6	8.6	8.6	8.7
3	8.7	8.6	8.8	8.8
4	8.6	8.6	8.7	8.8
5	8.7	8.7	8.7	8.5
6	8.6	8.7	8.5	8.6
7	8.5	8.8	8.7	8.8
Min	8.5	8.6	8.5	8.5
Max	8.7	8.8	8.8	8.8
Average	8.6	8.7	8.7	8.7
StDev	0.08	0.08	0.10	0.12

Flashing Response on Evaluated Lead Bend Height:

3.4 Use the PDCA to execute the project

With the results of rootcause definition and validation, the following actions are defined per Plan-Do-Check-Act method:





Fig 18: Mold Shot response per Lead bend height


4.0 RESULTS AND DISCUSSION

4.1 Evaluation Summary

Board Height	Device No	Lot No	Run Quantity	3rd Jet Yield	Model Start Flushing Response (hr/flush)	Sampling Deviation Time (secs/lot)	DCI Test (secs/lot)						Air Opt Yield	Electrical Test Yield (%)
							Pre-Model	Post-Model	Post-PMC	Post-Paste	Post Sinteration	FT DCI Test		
8.5 mils (Def-Ran- Evaluation)	MP1A21SFA1803AB	T3020090-1	240	98.75%	36/48	48/48	47/48	47/48	47/48	47/48	47/48	45/47	99.16%	77.8%
10 mils	MP1A21SFA1803AB	T3020090-1	240	98.33%	3/48	48/48	47/48	48/48	47/48	46/48	46/48	46/48	100%	74.3%
8.5 mils (Def-Ran- Validation)	MP1A21SFA1803AB	T3020090-1	480	97.92%	30/48	48/48	47/48	47/48	47/48	46/48	46/48	44/48	99.79%	93.3%
8.5 mils (Def- Re-sampling)	MP1A21SFA1803AB	U1250076	181	95.58%	47/48	32/32	48/48	48/48	48/48	48/48	43/48	41/48	100.00%	85.5%
8.5 mils (Def- Re-sampling)	MP1A21SFA193CA412	U1261239-1	289	95.17%	48/48	32/32	48/48	48/48	48/48	48/48	48/48	48/48	100.00%	
8.5 mils (Def- Re-sampling)	MP1A21SFA1803AB	SA205049-4	139	96.40%	33/48	32/32	47/48	46/48	46/48	46/48	43/48	36/48	100.00%	85.6%

3.5 Project Implementation

3.5.1 PLAD15KPCA Lead bend height Change



1. All bent straps passed bend height initial specification window of 7.5-9.5 mils.
2. Minimal thick flashing on heatsink observed on all strips molded for 8.5 mils bend. For 10 mils - 90% of the units have thick flashing on heatsink.

32nd ASEMPE National Technical Symposium

- Low IR failure noted on DC Test conducted on identified Assembly process (Mold-Form) for 8.5mils bend repeatability evaluation.
- No significant difference on Electrical Test yield between original and modified lad bend.


- Identified the root cause of excessive flashing and its solution which is lead bend height modification.
- UPH improvement in PLAD Manual Deflash process by 38.58%.

4.2 Project Impact: UPH/ Quality


- Cost avoidance of \$ 2.785K on process costs for 160000 units.

- UPH Improvement of 38.58% from 78 UPH to 127 UPH:

PACKAGE	DESCRIPTION	UPH	PROCESS COST PER UNIT	VOLUME 2022	COST PER PROCESS	COST IMPROVEMENT	UPH IMPROVEMENT
PLAD-15KP	ORIGINAL	186	\$0.0189	160,000	\$3,027.96	\$2,785.86	38.58%
	BK DIE - 87.7% FLASHING	78	\$0.0451		\$7,220.51		
	33% FLASHING	127	\$0.0277		\$4,434.65		



- Package chip-out PPM reduction from 3 KPPM to 0.37 KPPM. New lead bend height implemented last October '2021.



4.3 Tangible / Intangible benefits

- Improved cycle time in Manual Deflash process.
- Ease of flashing removal for the production operators.
- Reduce package chip-out defect ppm.

5.0 CONCLUSION

Based on study and evaluation conducted, the following project objectives were attained:

6.0 RECOMMENDATIONS

It is recommended to fan-out 8.5 mils bend height improvements to other single-die/ bi-directional devices (15KPCA). It is also recommended to study and conduct same evaluation on other PLAD devices with same flashing manifestations.

7.0 ACKNOWLEDGMENT

The authors acknowledge:

Wally Agcambert and Rica Medrano for their approval, support and motivation of this project.

Fastech IE, Mr. Alexis de Torres on his support and contribution for the completion of this project.

EOL-Line Maintenance Group for mold set-up and adjustments of PLAD Mold Press and mold chases.

Niche Assembly and PLAD Mold Production Supervisors and Operators for their Support.

Test Engineers for the support on this evaluations.

8.0 REFERENCES

- Technical Data Sheet – Surface Mount Transient Voltage Suppressor, MPLAD30KP14A-MPLAD30KP400CA.
- Technical Data Sheet – EMC

9.0 ABOUT THE AUTHORS



Jason Sison is currently assigned in EOL Process Engineering; handling Niche and Small Black products

32nd ASEMEP National Technical Symposium

as Process Engineer. A Fastech team member since July 13, 2015



Primitivo L. Regencia Jr. is currently assigned in EOL Process Engineering as EOL PE Supervisor He joined Fastech since February 01, 2013