LEADFRAME TAPE DE-REEL PREVENTION AT WIREBOND MACHINE THROUGH SENSOR INTEGRATION

Bernard R. Zamora Eric G. Espino Julius A. Andal

Integrated Lines Operations 1 STMicroelectronics, Inc. 9 Mountain Drive, LISP 2, Calamba 4027 Laguna, Philippines, bernard.zamora1@st.com, eric.espino@st.com, julius.andal@st.com

ABSTRACT

Sensor technology plays a major role in the Semiconductor Industry, it can accelerate processes, increase productivity, and prevent losses. This technical paper will discuss how we prevented the Lead frame tape De-reel at Reel-to-Reel Wirebond process by integrating detection control through sensor with latching relay and lever roller at input/output module. Using Problem Solving Methodology, the team was able to identify and analyze the root causes on how the lead frame tape de-reel happened during wirebond process including how the solution prevented the defect through error proofing concept.

1.0 INTRODUCTION

Micromodule device is one of company's high volume production lines. The volume ramp-up is very challenging. Department KPI should be met by putting all controls in the line to meet target Yield.

Yield graph shows that it's not consistently meeting the target of 99.80% versus actual yield from Oct'19 to Mar'20 as shown in Fig.1



Fig. 1. Micromodule Assy Yield from Oct 2019 to Mar 2020

Analyzing the Yield detractor, it shows that crumpled Lead frame tape due to de-reeled lead frame at Wirebond process is the top defect in pareto chart as shown in Fig.2





Figure 3 shows PPM trend of lead frame De-reel at Wirebond averaging 21038 PPM for Micromodule devices from October 2019 to March 2020. The target is to reduce the crumpled leadframe PPM level to 19892 PPM.



Fig. 3. Lead frame tape de-reel PPM from Oct 2019 to Mar 2020

2.0 REVIEW OF RELATED WORK

"Not Applicable"

3.0 METHODOLOGY

3.1 Analyzing the Process Flow

Fig. 4 is the Process macro map of Micromodule device from Assembly to Final test where Wirebond is the focus of this project and the main source of Yield top defect.



Fig. 4. Micromodule Process Macro Map

Fig. 5 is the process flow of Wirebond Reel-to-Reel from lot preparation to unloading of wirebonded units at metal reel where de-reel happened during wirebond process.



Fig. 5. Detailed Reel to Reel Process Flow

3.1.1 Reel to Reel Wirebond Process

Reel to Reel wirebond machine with Input and Output spooler. Lead frame tape with un-bonded units is connected to input yellow spacer, while the bonded units is connected to output yellow space as shown in Fig.6



Fig. 6. Reel to Reel iHawk Xtreme Wirebond Machine

3.1.2 What is de-reel at Wirebond?

Fig. 7 shows the event of de-reel lead frame tape at Wirebond. This scenario happens at input/output of spooler, where the sensor encounters malfunctioning resulting to continues stepper motor movement. This machine malfunction will cause the lead frame tape to slide into the floor where bonded and unbonded units hit the hard surface.



Fig. 7. De-reel Lead Frame tape event at Wirebond

33rd ASEMEP National Technical Symposium

The assembly defect manifestation was encountered after dereel at Wirebond which is failed at Final test and potential customer complaint as shown in Fig.8



Fig. 8. Lead frame tape de-reel defects.

3.2 Identification of Potential Rootcause

Fig.9 is the Cause-and-Effect diagram of De-reel Lead frame tape at Wirebond. Team identified 9x potential root causes that contribute to the problem or defect.



Fig. 9. Cause and Effect diagram.

Table 1 shows the validation of potential root causes which identified at cause-and-effect diagram. The team identified 5 potential root causes namely blurred sensor reflector, sensor malfunction, input/output motor malfunction, adhesive tape attached to yellow spacer and warp metal reel which are all true cause and within control.

Table 1. Root causes validation

<u>Potential</u> Cause	Method of Validation	Result of Validation	Conclusion (True Cause/Not True Cause)	Controllability
Blurred sensor reflector	Visual simulation	Verified that reflector at FWB1105 is blurred	True cause	Within Control
Sensor malfunction	Visual simulation	Verified that sensor is possible to malfunction due to short circuit	True cause	Within Control
Input/output motor malfunction	Visual simulation	Verified that input/motor is prone to malfunction due to manual rotate of stepper motor	True cause	Within Control
Warp/damaged metal reel	Visual inspection and digital caliper	Some of metal reel have damaged on the gap that sometimes will cause crumpled to LF, affected by warp is failed on target gap measurement	True cause	Within Control
Adhesive tape attached to yellow spacer	Visual inspection	Most of yellow spacer have many spliced and the attached tape is not totally adhere to yellow spacer	True cause	Within Control
Operator not properly load the metal reel to spooler	Visual inspection	All in-process metal reel is properly load	Not true cause	No Control
wom-out yellow spacer	Visual inspection	All worn out yellow spacer is already pull out in the line	Not true cause	Within Control
Damage yellow spacer reel	Visual inspection	All damaged yellow spacer is already pull out in the line	Not true cause	Within Control
Not certified operator	Certification badge	All operator at WB is certified	Not true cause	Within Control

3.3 Solution Formulation

Table 2 shows 5 identified valid causes of Lead frame tape de-reel at Wirebond process. The authors list down all the alternative solutions for the valid causes for which 2x alternative solutions (1. Use lever type roller to improve sensor sensitivity 2. Use additional sensor with latching relay) was identified with highest rating based on effectiveness of measure under the criteria of risk, ease and cost. Risk is potential to create problem if implementing the solution. Ease of implementation is about how easy it is to implement the solution. While the Cost is referred to the expenses associated to execution of solution.

Table 2. Selection of Best alternative Solutions.

	Ę			Validation				Measures for Effectiveness			
Valid Cause	Level	Alternative Solutions	Category	Method	Results	Risk	Ease	Cost	Rating	Rank	Go / No Go
Blurred sensor reflector	3	Use lever type roller to improve sensor sensitivity	Bench	Installed lever type roller	12 out 12 of machine already installed lever type roller	5	5	5	15	1	Go
Sensor malfunction	1	Use additional sensor with latching relay	innovative	Installed additional sensor with latching relay	3 out 12 of machine already installed sensor with latching relay	5	5	5	15	2	Go
Input/output motor malfunction	4	Motor response checking during PM	Bench	Include at PM checklist	Not yet included	3	3	3	9	6	No go
Adhesive tape attached to yellow	1	Use additional sensor with latching relay	innovativ	Installed additional sensor with latching relay	3 out 12 of machine already installed sensor with latching relay	5	5	5	15	3	Go
spacer	4	Remove tape at yellow spacer prior use	/e	Conduct awareness across all shift	Done on deployment but still have de reel due to other reason	5	1	5	11	4	No go
Warp metal reel	4	Pull out all warp metal reel and conduct monthly checking of metal reel	innovati ve	MH perform inventory and checking of metal reel condition	8 out of 104 pcs of metal reel is defective	3	3	5	11	5	No go

Potential Problem Analysis was used to determine the risks prior the implementing of best solution to ensure that the best solutions will not incur new problems as shown in table 3

Table 3. Potential Problem Analysis

Best solution	Potential Problem	Potential Cause	Preventive/ Contingency Acton	EP Level	Responsible	Target	Sta
Use lever type roller to improve sensor sensitivity	Stuck-up lever type roller	Misaligned aluminum holder	Include checking of lever type roller at PM checklist	3	J. Andal/B. Zamora	WW2015	Do
	Sensor malfunction	 Frequent use 	 Provide spare of photoelectric sensor Include checking of sensor at PM checklist 	2	J. Andal	WW2015	Do
Use additional sensor with latching relay	Malfunction of 24V relay	 Short circuit 	 Provide spare of 24V relay Include checking of 24V relay at PM checklist 	2	J. Andal	WW2021	Do
	No 24V supply of sensor	Defective 24V machine power supply	 Include checking of 24V machine power supply at PM checklist Install another relay for machine power supply for zero volts detection 	2	J. Andal	WW2021	Do

3.4. Description of Best Solution

Figure 10 shows the location of installed reflective sensor at input and output module of Wirebond machine. This sensor has a latching relay set-up, the spooler motor automatic turnoff once the sensor sense Lead Frame tape on a required limit.

The machine will not run/start until the "press reset" was not activated refer to fig 11. A lever type roller was installed at the lower part of metal reel to improve sensor sensitivity.

With this sensor installed, de-reel event was prevented and falling lead frame tape on the floor was eliminated.



Fig. 10. Location of sensor and lever as additional control



Fig. 11. Press reset motor activation button

3.5 How does a reflective object sensor work

When light from the Emitter strikes the sensing object, the object reflects the light, and it enters the Receiver where the intensity of light is increased. This increase in light intensity is used to detect the object. Sensing distance ranging from several centimeters to several meters as shown on Fig 12.



Fig. 12. De-reel Lead frame Sensor

3.6 How does lever roller work

The lever roller provides enough tension on the output spacer and improves the detection of spacer on the reflective sensor line of sight as shown on Fig 13.



Fig. 13. Lever roller at input/output

OUTPUT SPACER REEL MOTOR MODULE

33rd ASEMEP National Technical Symposium

3.7 Electrical wiring diagram at input/output

Figure 14 shows that when any of two sensors are triggered or activated the relay will be activated on latching state, cutting the input motor supply and will prompt *LF reel sensor check failed*.



Figure 15 shows that when the sensor is triggered or activated the relay will be activated in a latching state, cutting the output motor supply and will prompt *output LF error*.





Fig. 14. Input Wiring diagram.

3.8 Solution Implementation

Table 4 shows the implementation plan of the best solution identified by the team. Using PDCA (Plan Do Check Act), we will be able to check the over-all status of activity to implement the best solution.

First best solution is installation of lever type roller to improve sensor sensitivity was identified 3 steps on how to execute the activity. Those are design creation of lever type roller, in-house fabrication of lever type roller and lastly Installation/evaluation. Implementation is 100% done according to the plan.

Second best solution is installation of additional sensor with latching relay was identified with 4 steps on how execute the activity. Those are design electrical wiring diagram, Gathering materials, installation/evaluation, and lastly implementation of additional sensor with latching relay to all machines. Implementation is 100% done according to the plan.

Table 4. Implementation Plan

PLAN		DO										CHECK	ACT	
	Steps	Implementation Date (When)									Resp.		Learning (What you	01-11-2
Best Solution	(How)	Plan vs. Actual	Wk	Mar-2 Wk	U Wk	Ap Wk	r-20 Wk	r Wk	way-2 Wk	(Who)		Result Monitoring (How)	learned from the action)	Status
	Design creation of lever	Plan	10								L A malal	Brainstorming and suggested	Team	100%
Use lever type roller	type roller	Actual	10								J. Andai	roller	communication	done
to improve sensor sensitivity	In-house fabrication of lever	Plan	11								J. Andal	100% completion of	Project execution	100%
	type roller	Actual	11									tabrication		done
	Installation and evaluation	Plan Actual		12 12							Team	Monitoring the effectiveness of lever roller	Always set a another best action	100% done
	Design electrical wiring diagram	Plan Actual			13 13						J. Andal	Checked functionality of design wiring diagram	Learned reading of Electrical wiring diagram	100% done
Installed additional	Gathering materials	<mark>Plan</mark> Actual				<mark>15</mark> 15					J. Andal	With available materials	Material preparation	100% done
sensor with latching relay	Installation and evaluation	Plan Actual					16 16				J. Andal/B. Zamora	Installed and evaluate the effectiveness of additional sensor	Project execution	100% done
	Implementation of additional sensor with latching relay to all machine	Plan Actual						18	<mark>19</mark> 19	20 20	J. Andal/B. Zamora	3 WB installed sensor with latching relay have no occurrence of dereel	Project execution	100% done

33rd ASEMEP National Technical Symposium

4.0 RESULTS AND DISCUSSION

Graph shows at fig 16 that after the implementation of best solution, the lead frame tape de-reel event at Wirebond was eliminated starting April 2020 to June 2022.



Fig. 16. De-reel event trend after installation

The IE Certified Annualized cost saving for this project from April 2020 to March 2021 was calculated at 73.62KUSD for all Micromodule devices as shown at table 5.

Table 5. Annualized Cost Savings

YIELD IMPROVEMENT / SCRAP REDUCTION PROJECT														
Project	Dereel problen	m at Wirebond PPM												
	Actual Forecasted													
Monthly Forecast Savings		Apr'20	May'20	Jun'20	Jul'20	Aug'20	Sep'20	Oct'20	Nov'20	Dec'20	Jan'21	Feb'21	Mar'21	Te
Input Volume (K)		13,061	13,603	6,379	12,118	15,340	11,884	10,977	6,071	5,950	6,399	7,285	4,971	114
Defect rate (%)														
	Baseline	2.34%	2.34%	2.34%	2.34%	2.34%	2.34%	2.34%	2.34%	2.34%	2.34%	2.34%	2.34%	1
A	ctual/Target	0.00%	0.00%	0.00%	0.00%	0.00%	1.64%	1.64%	1.64%	1.64%	1.64%	1.64%	1.64%	1
	mprovement	2.34%	2.34%	2.34%	2.34%	2.34%	0.70%	0.70%	0.70%	0.70%	0.70%	0.70%	0.70%	
			-				-					-		_
Scrap qty reduced (K)		305.47	318.14	149.18	283.42	358.78	83.38	77.02	42.6	41.75	44.89	51.11	34.88	1,7
						_				-				
Device Cost		0.0409	0.0428	0.0419	0.043	0.0427	0.0419	0.0366	0.0351	0.0345	0.0345	0.0345	0.0345	1
Savings (K\$)														
	Monthly	12.49	13.6	6.25	12.18	15.34	3.5	2.82	1.49	1.44	1.55	1.76	1.2	7:
	Cumulative	12.49	26.09	32.34	44.52	59.86	63.35	66.17	67.66	69.1	70.65	72.42	73.62	
				-								-		
		Project		·										
RESPONSIBILITY MATRIX	IE	Owner		i IE	CERT	'IFIEI								
CCRP Release #	n/a	B. Zamora		·			·							
Actual + Forecasted	70.00				_									
Savings (K\$)	/3.6Z													

4.1 Team Learnings:

Table 6 shows the team learnings that need to improve.

Table 6. Team Learnigs

What Went Well	What Needs to Be Improved	Action Plans	RESP	Target Date	Status
Eliminate dereel at input and output module of Wirebond machine	Parts maintenance of implemented project	Include proper maintenance at PM checklist	J. Andal B. Zamora	WW2021	Done
Prevent broken coupling due to manual rotation of metal reel during end of lot	100% installation of dereel prevention project	Stick to timeline activity installation	J. Andal B. Zamora	WW2022	Done

4.2 Standardization:

The team list down all needed documents activities to sustain the improvements, applicable documents were updated. Then successfully deployment to the shopfloor personnel was executed. Table 6 shows the summary of documents and activities that have been updated.

Table 7. Documentation

Activity	Responsible	Target Implementation	Status
Update Wirebond work instruction	Bernard Zamora	WW2023	Done
Providing OPL on how to use dereel prevention project	Bernard Zamora	WW2022	Done
Line training for dereel prevention project	Julius Andal / Eric espino	WW2021	Done

5.0 CONCLUSION

After installing the reflective sensor with latching relay and lever roller at input/output module, the lead frame tape dereel event at reel-to-reel Wirebond process was eliminated.

6.0 RECOMMENDATIONS

It is recommended to fan-out these learnings to other machines. Future studies are recommended for plans to zeroout the occurrences of de-reel event at Wirebond.

7.0 ACKNOWLEDGMENT

We would like to thank Mr. Leonel Jay Manuel and all the Integrated Lines Team for their sincerest appreciation and full extended support.

To our colleagues for providing us with the tools necessary to complete this project.

To our beloved family, friends, and colleagues who wholeheartedly supported them to make this project fruitful and successful.

8.0 REFERENCES

ASM iHawk Eagle Extreme Wirebond Maintenance Manual

9.0 ABOUT THE AUTHORS



Bernard R. Zamora graduated B.S. in Industrial Engineering at University of Batangas and graduate of B.S. in Information technology at Laguna State Polytechnic University. He has 15 years of experience in Semiconductor and Solar manufacturing focusing on Process Engineering. He is currently a Sr. Process Engineering Technician at Finish Integrated Lines at STMicroelectronics, Inc.



Julius A. Andal, Technician Specialist. Graduate of threeyear Electronics Technology in Enverga University Foundation, Inc. Candelaria. He has 19 years of Semiconductor Manufacturing Focusing on Equipment line sustaining, Preventive Maintenance and Project Management under Equipment Group in OPS-1 at STMicroelectronics, Inc



Eric G. Espino is a Senior Process Test and Finish Engineer in Test Product Engineering. BS Electronics and Communications Engineering from the Computronix College Dagupan. Certified Six-Sigma Green Belt practitioner currently employed at STMicroelectronics, Inc. with 24 years in Semiconductor Industry.