MODEL "S" YIELD IMPROVEMENT THROUGH FAILED ADJUST REJECT REDUCTION

Jerry B. Abitong, Jr. Angelito F. Manos, Jr.

Research and Development – NPI Department, MedTech and Specialty Audio Knowles Electronics (Philippines) Corporation, Cebu Light Industrial Park, Basak, Lapu-Lapu City, Cebu JerryJr.Abitong@knowles.com AngelitoJr.Manos@knowles.com

ABSTRACT

The current trends of manufacturing industries are expected to face economic uncertainty driven by supply chain disruptions, constant workforce job-hopping, and economic recessions. The role of the New Production Introduction Team, aside from developing a cost-effective product design, is vital to combat the negative impact of those uncertainties by introducing breakthrough ideas for process controls and procedures that are resistant to frequent changes and disruptions in the assembly line. This is crucial to achieve the best quality performance, reduce or eliminate scrap, and increase productivity.

This paper discusses the utilization of various Engineering solutions and statistical analysis tools at Knowles Electronics Philippines to effectively improve the yield performance of Model S thereby greatly improving the company's financial status in terms of scrap cost. Actions and lessons learned in this paper were then set as a baseline for future NPI projects.

1.0 INTRODUCTION

The concept of Balanced Armature (BA) drivers lies in the principle of electromagnetism which uses an electrical domain to vibrate a tiny metal reed that serves as the mechanical domain connected to a thin metal sheet to produce an acoustical domain. Figure 1 illustrates the fundamental concept of BAs.



Fig 1. Balanced Armature Driver Energy Transfer Illustration

Balanced Armature (BA) drivers are used for a wide range of applications in Medical Technology and Specialty Audio and one of the major components of hearing aids, earphones, and in-ear monitors (see Figure 2).



Fig 2. Application of Balanced Armature (BA) Drivers

A BA driver must maintain an ideal balance between its components, especially the gap between magnets and reed to provide the best acoustic performance as shown in Figure 3. Each component has its unique function and the tiniest error in its assembly could deteriorate the sound it produces.



Fig 3. Major Components of Balanced Armature (BA) Drivers

To make a BA driver functional, it needs to be adjusted to the desired set point so that it can produce the targeted sound pressure level. A functional test is then conducted that sweeps through different acoustic parameters that are critical to the customer.



Fig 4. Illustration of Electro-mechanical Adjustment of BA Driver

If a BA driver cannot be adjusted, it will not be responsive during acoustic testing and will be rejected as *"Failed Adjust"*, which means that there is a problem causing the reed and other components not to move properly.

In this paper, a series of structured analyses utilizing Lean Six Sigma principles, and DMAIC methodology was utilized to significantly reduce the Failed Adjust rejection on Model S.

2.0 REVIEW OF RELATED WORK

Not applicable

3.0 METHODOLOGY

This paper utilizes the DMAIC methodology to effectively reduce the Failed Adjust rejection of Model S.

<u> 3.1 DMAIC – Define Phase</u>

3.1.1 Problem Statement

As shown in Figure 5, Model S is having low yield rate performance with only 84.2% for January 2023, which is off its monthly target of 88.0%.



Fig 5. Model S yield performance and target

3.1.2 Project Objective

To avoid further scrap penalties, Failed Adjust (FA) rejection must be decreased by half to increase the yield performance of Model S from 84.7% to 94.0% until the end of March 2023.

<u> 3.2 DMAIC – Measure</u>

3.2.1 Yield Performance

The average yield performance of Model S based on Oracle Vigilance Analytics Data is only at 84.23%, which is off by 3.4% from the January target of 88.0% (Figure 6).



Fig 6. Model S Yield Performance

Based on the Pareto of failures (Figure 7), the main contributor to this low yield performance is Failed Adjust (FA) reject at 13.63% rejection rate, which comprises 92% of the overall rejects for Model S.

Rej	ects%											
	14.00 -	_		-	-							
	12.00 -											
			Metrics: FA									
	10.00 -		Rejects%i 13.63									
	8.00 -											
	6.00											
	4.00											
	2.00 -											
	0.00 -							_				
		FA	DISTORTION	EUL	GROUND	OPEN	BUZZ	IMPEDANCE	DCR	HEP	LHE	

Fig 7. Pareto of Rejects for Model S

3.2 DMAIC – Analyze

On the macro process flow chart below (Figure 8), Failed Adjust (FA) is detected on the Adjust and Test Process where the acoustic testing is being performed.



Fig 8. Model S Process Flow Chart

By formulating a fishbone diagram (Figure 9) through Cross-Functional Team brainstorming, obtaining significant inputs from the PFMEA, and adopting lessons learned from other models, several potential root causes have been listed below based on the various 5Ms + 1E (measurement, material, man, method, machine, environment).



Fig 9. Fishbone Diagram for Failed Adjust

Before root cause validation, a screening was performed by rating it from (1) as the lowest and (5) as the highest on its likeliness to occur and the complexity of validation. All causes with a product of fifteen (15) and above will be prioritized during validation as reflected in Table 1.

Table 1. Potential Root Cause Screening Prioritization

Factor		Potential R	oot Causes	Rating	Score	
Machine	Not optim	ized reed welding	parameter	vv	25	
Measurement	Mismatch	ed rubber sea		sv	15	
Material	Reed har	iness	VS	15		
Material	Yoke gap			SS	9	
Machine	Not optim	ized shim welding	parameter	SS	9	
Method	Lacking c	riteria		NV	9	
Measurement	Incorrect	configuration	NV	5		
Environment	Temperat	ure issue	NV	5		
Environment	Humidity i	ssue	NV	5		
Material	Bad yoke	NV	5			
Man	NV	5				
Man	New oper	ator		NV	5	
Method	SPC not f	ollowed		NS	3	
Machine	Reed wel	ding fixture issue		SN	3	
Machine	Shim well	ling fixture issue		SN	3	
Man	Bad judge	ment		SN	3	
Material	Diaphrag	n forming issue		NN	1	
Occurre	nce	Score	Complexity	S	core	
V - Very Likely		5	V = Very Easy		5	
S = Somewhat L	ikely	3	S = Somewhat Easy	3		
N = Not Likely 1			N = Not Easy	1		

3.2.1 Root Cause Validation

3.2.1.1 Machine: Reed Welding Machine Parameter Not Fully Optimized

The current parameter of reed welding is set based on three factors which are: Power, Weld Force (Left), and Weld Force (Right). Further understanding the product's mechanism, it then came into consideration to include the position of the welding point as one of the parameters.

The product structure follows the concept of a cantilever beam (Figure 10) where the weld point serves as the fixed end and the tip of the reed serves as the free end.



Fig 10. Comparison of a Cantilever Beam to BA Product Construction

3.2.1.1.1 Data Gathering

One week of data on welding position from Electronic Statistical Process Control (E-SPC) (Appendix A) was obtained to be correlated to the daily rejection rate of Failed Adjust (FA).

3.2.1.1.2 Validation

3.2.1.1.2.1 Normality Test

Normality testing (Figure 11) showed that the P-value is at 0.935, which is higher than the set alpha level of 0.05, thus, the test result failed to reject the null hypothesis (H_o) and validated that the data gathered for welding location follows the normal distribution.



Fig 11. Probability Plot of Welding Location

3.2.1.1.2.2 Regression Analysis

The regression model as shown in Figure 12, shows a P-value of 0.000, which is lower than the alpha level of 0.05, thus, the Null Hypothesis (H_o) is rejected and confirmed that the relationship between Failed Adjust (FA) rejection and Welding Location is statistically significant.

gression Analys	is. rai	ieu Au	just (r	A) Keje	Ct 70 V	ersus welding Location	. (
Regression Equatio	n						
Failed Adjust (FA) Reject 9		20.80 + 4	5.64 Weld	ing Locatio	n (mm)		
Coefficients							
Term	Coef	SE Cor	f T-Val	ue P-Val	lue VIE		
Constant	-20.80	3.0	4 -6.	.84 0.0	200		
Welding Location (mm)	45.64	5.2	4 8	.70 0.0	000 1.00		
Model Summary <u>S R-sq R</u> 0.942584 76.71%	sq(adj) 75.70%	R-sq(pi 72.	ed) 72%				
ranary sis or randine.	DE	Adi 55	Adi MS	E-Value	P-Value		
Source			12 0000	78.76	0.000		
Source Regression	1	67.30	67.2989	12.12	0.000		
Source Regression Welding Location (mm)	1	67.30 67.30	67.2969	75.75	0.000		
Source Regression Welding Location (mm) Error	1 1 23	67.30 67.30 20.43	67.2989 67.2989 0.8885	75.75	0.000		

Fig 12. Regression Analysis Result of Welding Location and Failed Adjust

3.2.1.1.3 Root Cause Conclusion

Based on the statistical analysis conducted, it is concluded that welding location is a valid root cause of Failed Adjust (FA) rejection.

3.2.1.2 Measurement: Mismatched Rubber Seal

The rubber seal is used to prevent air leakage from the Balanced Armature (BA) driver to the coupler. It also ensures a smooth flow of acoustic signal into the testing machine. The illustration in Figure 13 shows how the BA driver is integrated into the coupler.



Fig 13. BA Receiver and Coupler Integration

3.2.1.2.1 Data Gathering

It was found that the current coupler is using an old design rubber seal which has a circular hole with only 0.0962 mm² compared to the BA Receiver hole which is at 0.767 mm² (Figure 15). This shows that there is a partial blockage of acoustic signals due to the shape of the rubber seal hole.



Fig 14. BA Receiver and Rubber Seal Airflow Area Computation

3.2.1.2.2 Validation

Checking the acoustic response graph (Figure 15) of the BA driver, we can observe that there is a glitch near Peak 2. This signifies that the issue is most probably related to air tubing or path.



Fig 15. Electroacoustic Response Graph of Model S

3.2.1.2.3 Root Cause Conclusion

It is concluded that the rubber seal used is mismatched with the BA Receiver and is a valid root cause of Failed Adjust (FA) rejection.

3.2.1.3 Material: Difference in Reed Hardness

A BA driver is essentially a complicated Spring-Mass system where:

Mass (m)	= amount of "stuff" that moves,
Stiffness (k)	= summation of all "springs" in the system
Damping (B)	= friction and other losses
Force (f)	= the electric signal moving on the coil
Distance (x)	= the displacement of armature



Fig 16. Illustration of Spring-Mass System

The reed functions as the spring, in which its material integrity, especially its hardness, is very important to the BA driver's electro-acoustic performance.

3.2.1.3.1 Data Gathering

During failure analysis, it was observed that good units have larger granular pattern compared to the bad units as shown in Figure 17.



Fig 17: Illustration of Grain Pattern

A hardness test (Appendix B) is conducted in each unit for further verification.

3.2.1.3.2 Validation

3.2.1.3.2.1 Normality Test

The results shown in Figure 18 reflect that the P-value of reed hardness for Good units and Bad units are at 0.058 and 0.067, which are higher than the set alpha level of 0.05, thus, the test failed to reject the null hypothesis (H_o) and validated that the data gathered for Reed Hardness on both materials follow the normal distribution.



Fig 18: Normality test for Reed Hardness of Good and Bad units

3.2.1.3.2.2 Hypothesis Testing – 2-sample t-Test

Performing a 2-sample t-test (Figure 19) resulted in a P-Value of 0.227, which is higher than the set alpha level of 0.05, thus, the test result failed to reject the null hypothesis (H_0) and confirmed that there is no significant difference between the mean of reed hardness of Good units and Bad units.



Fig 19. Hypothesis Testing – 2-Sample t-Test for Reed Hardness of Good and Bad units

3.2.1.3.3 Conclusion

It is concluded that the reed hardness is not a valid root cause for Failed Adjust (FA) rejection.

4.0 RESULTS AND DISCUSSION

4.1 Root Cause Validation Summary

After a series of validation activities, there were remaining two (2) valid Potential Root Causes as shown in Table 2. The

other validation results of the other factors can be found in the Appendix Section.

Table 2.	Root Caus	e Validation	Table Summar

Potential Root Causes	Verification	Target	Result	Status	Remarks
Bad SFYTunnel Height	Check actual turnel height in comparison to print specification	20-Jan	Invalid	Closed	All are within specification
Big dovetail gap	Run evaluation small gap and bigger gap	22-Jan	Invalid	Closed	No significant difference on the result of both condition
Bad OPD Forming	Run samples with limit bad forming to perfect forming material	samples with limit bad forming to perfect forming material 21-Jan		Closed	No significant difference on the result of both condition
Reed hardness issue	Run evaluation for different grain condition of reed	22-Jan	Invalid	Closed	No significant difference on the result of both condition
Bad judgement on visual criteria	Conduct MSA on operator's visual judgement	22-Jan	Invalid	Closed	Operator passed the MSA
New operator	Confirm operator's training record	18-Jan	Invalid	Closed	Veteran operator's running in RAI
Operator not certified	Confirm operator's training record	18-Jan	Invalid	Closed	Operator's are trained and certified
ESPC not followed	Confirm ESPC data	22-Jan	Invalid	Closed	ESPC is performed and updated
Lacking criteria	Confirm machine IPQC if can filter misalignment of camera	26-Jan	Invalid	Closed	Camera alignment checking is included in PFMEA
Reed Welding Machine parameter not fully optimized	Confirm history of reed welding parameters implemented	29-Jan	Valid	Closed	Reed welding parameters not fully optimized
Reed Welding Fidure issue	Check buy off history of reed welding	27-Jan	Invalid	Closed	Reed welding buy off passed
Shim Welding Foture issue	Check buy off history of reed welding	27-Jan	Invalid	Closed	Shim welding buy-off passed
Shim Welding Machine parameter not fully optimized	Confirm history of reed welding parameters implemented	29-Jan	Invalid	Closed	Machine parameters are optimized
Incorrect FCAAT fisture	Confirm actual FCAAT foture	22-Jan	Invalid	Closed	Correct FCAAT foture used
Incorrect FCAAT coupler	Confirm actual FCAAT coupler	22-Jan	Invalid	Closed	Correct FCAAT coupler used
t Incorrect Rubber seal Confirm actual FC/AT rubber seal		22-Jan	Valid	Closed	Rubber seal shape is does not coincide with the sound port
Mistake test configuration	Confirm actual FCAAT test configuration	22-Jan	Invalid	Closed	Correct FCAAT test configuration used
Temperature Issue	Confirm historical temperature data	20-Jan	Invalid	Closed	No significant changes on the temperature data
HumidityIssue	Confirm historical humidity data	20-Jan	Invalid	Closed	No significant changes on the humidity data
	Peterdi Foto Clause 48 771 una 1 legit 19 disal agn 184 791 mari legit	Description Verification Let PT-Inter letter Casc and branch letter letter assesses perstranders Exp PT-Inter letter Rate and branch letter letter assesses perstranders Exp Officient letter Rate and branch letter letter assesses perstranders Exp Officient letter Rate and branch letter letter assesses perstranders Rate and branch letter letter assesses Rate and branch letter letter assesses Rate and branch letter letter assesses Rate and branch letter letter assesses Rate and branch letter letter assesses Rate and branch letter letter assesses Rate and letter assesses Rate and letter assesses Rate and letter assesses Rate and letter assesses Rate Marcia Marcel Casion marcher Xall Letter assesses Rate Marcia Marcel Casion marcher Xall Letter assesses Rate Marcia Marcel Casion marcher Xall Letter assesses Rate Marcel Marcel Casion marcher Xall Marcel Marcel Xall Marcel Casion marcel Marcel Xall Marcel Casio	Neuroid Roy Clause Withinition Target (2000) Les Philosen logical consequences beint spectralism (2000) Salan logical consequences beint spectralism (2000) Salan (2000) Big Philosen logical consequences beint spectralism consequences beint spectralism Restandistical training spectralism consequences (2000) Salan (2000) Big Spectralism consequences beint spectralism consequences (2000) Confit spectralism consequences (2000) Salan (2000) Big Spectralism constructions Confit spectralism consequences (2000) Salan (2000) Salan (2000) Big Spectralism constructions Confit spectralism conserves (2000) Salan (2000) Salan (2000) Big Spectralism constructivity constructiv	Operation in the second seco	Neuroid Roc Classes Workfaction Target Read Statule Les PT-Invertified Chair abune hanging marginas party party family 33m Node Code Els PT-Invertified Part aduration large availage marginas party party family 33m Node Code Els PT-Invertified Randparts and party advantation types party code 33m Node Code Randparts and market party party family party family 3am Node Code Randparts market party family party family party family 3am Node Code Randparts market party family party family party family Code Code Code Code Randparts family party family

4.2 DMAIC – Improve

4.2.1 Mismatched Rubber Seal

Using the SCAMPER method (Figure 20), the rubber seal was modified from a circular shape to a rectangular shape to match the BA driver.



Fig 20. SCAMPER Table for Rubber Seal Improvement

4.2.1.1 Validation

The electroacoustic response graph in Figure 21 shows the comparison between circular rubber seal and rectangular rubber seal. It is observed that the glitch on the graph found on the circular rubber seal (yellow curve) at 2nd peak is eliminated in the graph of the rectangular rubber seal (purple curve).



Fig 21. Electro Acoustic Response Graph of Model S using Circular Rubber Seal and Rectangular Rubber Seal

Small scale validation run shows that the Failed Adjust (FA) rejection decreased from 15.0% to 6.4% as shown in Figure 22.



Fig 22. Model S Failed Adjust (FA) Rejection Trend

4.2.2 Not Optimized Reed Welding Parameter

4.2.3.1 Design of Experiment – Full Factorial

A full factorial design is performed based on the design as shown in Figure 23 and using four factors shown in Table 4.

Design Summary								
Factors:	4	Base Design:	4, 16					
Runs:	33	Replicates:	2					
Blocks:	1	Center pts (total):	1					

Fig 23. Full Factorial Design Summary of Reed Welding

Table 3. List of Factors for Reed Welding DOE

Factor	Name	Туре	Low	High
А	Weld Energy	Numeric	3	7
в	Weld Force (Left)	Numeric	1	3
с	Weld Force (Right)	Numeric	1	3
D	Weld Location	Numeric	0.5	0.7

Based on the Analysis of Variance (Figure 24), the model has a P-Value of 0.008 which confirms that the model is significantly the same with Factor A (Weld Energy), Factor D (Weld Location), and the 2-way interaction of Factors A and D.

Source	DF	Adj SS	Adj MS	F-Value	P-Value
Model	11	0.023950	0.002177	11.06	0.008
Linear	4	0.017541	0.004385	22,28	0.002
Weld Energy	1	0.007132	0.007132	36.23	0.002
Weld Head Force (Left)	1	0.001278	0.001278	6.49	0.05
Weld Head Force (Rigth)	1	0.000371	0.000371	1.88	0.22
Welding Location	1	0.008761	0.008761	44.50	0.00
2-Way Interactions	6	0.004525	0.000754	3.83	0.08
Weld Energy*Weld Head Force (Left)	1	0.000022	0.000022	0.11	0.75
Weld Energy*Weld Head Force (Rigth)	1	0.000653	0.000653	3.32	0.12
Weld Energy*Welding Location	1	0.002916	0.002916	14.81	0.01
Weld Head Force (Left)*Weld Head Force (Rigth)	1	0.000759	0.000759	3.86	0.10
Weld Head Force (Left)*Welding Location	1	0.000164	0.000164	0.83	0.40
Weld Head Force (Rigth)*Welding Location	1	0.000012	0.000012	0.06	0.81
Curvature	1	0.001884	0.001884	9.57	0.02
Error	5	0.000984	0.000197		
Total	16	0.024934			

Fig 24. Analysis of Variance of Factors

4.2.3.2 Response Optimization

The solution (Figure 25) shows a possible minimum Failed Adjust (FA) rejection of 5.28% with a Composite Desirability of 91.33%



Fig 25. DOE Response Optimization Result

A one (1) week validation run shows that the Failed Adjust (FA) rejection decreased from 4.0% to 2.0% as shown in Figure 26.



Fig 26. Model S Failed Adjust (FA) Rejection Trend

A series of validations and improvements led to a reduction of Failed Adjust (FA) rejection from 13.63% to 4.94%, which is a total of 63.76% improvement as shown in Figure 27.



Fig 27. Failed Adjust (FA) Rejection Trend (January to March 2023)

This contributes to an increase in yield rate for Model from 84.2% to 93.1%, which is a total of 10.57% improvement as shown in Figure 28.



Fig 28. Model S Yield Trend (January to March 2023)

The improvements helped the company save \$19,500 for scrap cost avoidance.

4.2 DMAIC – Control

With a series of root cause validations and improvements, it is a must to standardize and document all lessons learned and actions that have been implemented. The PFMEA (Figure 29) was updated to include that the proper rubber seal should be used for Model S with an RPN of 64.

Г						c		0	rrer	t Process			
No	Process Step/ Function	Requirement	Potential Failure Mode	Potential Effect(s) of Failure	Se verity	Classific at lo	Potential Cause(s) of Failure	Controls Prevention	Occurence	Controls Detection	Detection	RPN	Recommended Action
38	Adjust and Test	Good Units	Over Rejection	Distorion, LLF	8		Worn-out page pins	PM Monitoring	2	00C Sampling check, Golden Sample Checking, SUV, Preventive Maintenance, Calibration, 100% Functional Test	4	64	No action required
				Distorion	8		Incorrect fixture setup	Certified operators	2	00C Sampling check, Golden Sample Checking, SUV, Preventive Maintenance, Calibration, 100% Functional Test	4	64	No action required
				Failed Adjust	8		Incorect rubber seal used	Certified operators Indicate in work instruction	2	00C Sampling check, Golden Sample Checking, SUV, Preventive Maintenance, Calibration, 100% Functional Test	4	25	No action required

Fig 29. Updated PFMEA of Model S

In addition, the Reed Welding Recipe (Figure 30) has also been updated to standardize the use of optimized parameters.



Fig 30. Updated Equipment Parameter Matrix

5.0 CONCLUSION

The objective to reduce the rejection rate of Failed Adjust (FA) on Model S balanced armature driver by half was successfully achieved through the effective use of a structured Lean Six Sigma methodology and supported by statistical analysis. This was attained by improving the rubber seal design and effectively optimizing the reed weld process parameters to significantly reduce the Failed Adjust failure rate.

6.0 RECOMMENDATIONS

In a fast-paced industry where resolving the problem is of utmost priority, it is highly recommended to perform thorough Root Cause Screening before conducting factor validation. This is to immediately identify and resolve the main causes of the problem while validating less priority causes. It is also imperative that a structured analysis approach be performed through the use of problem-solving techniques supported by statistical tools to address the failures and define appropriate countermeasures.

7.0 ACKNOWLEDGMENT

The author would like to thank the Cross-Functional Team (CFT) including the Operators, Technicians, and Engineers for extending support on this project, as well as the Management Team of Knowles Electronics (Philippines) Corporation for the unwavering support on this project.

8.0 REFERENCES

- Knowles Electronics, LLC, Itasca, IL, USA, (2023). What is Balanced Armature? https://www.knowles.com/applications/earsolutions/premium-sound/what-is-balanced-armature
- 2. LibreTexts Physics, California State University, (2023). The Motion of a Spring-Mass System https://phys.libretexts.org/Bookshelves/University_Phy sics/

9.0 ABOUT THE AUTHORS



Jerry Abitong, Jr. is a graduate of the Technological University of the Philippines Visayas and a licensed Mechanical Engineer. He has been a Process Engineer at the Micro Actuator Technology Division of MinebeaMitsumi

Inc. for 7 years and is an Advanced Manufacturing Engineer at the MedTech and Specialty Audio (MSA) segment of Knowles Electronics (Philippines) Corporation for 2 years. He is a Certified Lean Six Sigma Green Belt and a TRIZ Level 1 Practitioner. He is already Six Sigma Black Belt trained and pursuing certification.



Angelito Manos, Jr. is a graduate of the Ateneo de Cagayan, Xavier University, Cagayan de Oro City Misamis Oriental and a licensed Electronics Engineer. He has been a Process Engineer at the Micro Actuator Technology Division of

MinebeaMitsumi Inc. for 7 years and is an Advanced Manufacturing Engineer at the MedTech and Specialty Audio (MSA) segment of Knowles Electronics (Philippines) Corporation for 2 years. He is a Certified Lean Six Sigma Green Belt and a TRIZ Level 1 Practitioner. He is also Six Sigma Black Belt trained and pursuing certification.

10.0 APPENDICES

Appendix A - Weld Location vs Failed Adjust Reject %

Welding Location (mm)	Failed Adjust (FA) Reject %
0.5044	2.0%
0.6122	7.0%
0.5295	3.7%
0.5420	4.4%
0.6228	5.9%
0.6026	5.8%
0.5781	4.6%
0.5738	4.9%
0.5502	4.6%
0.5797	4.6%
0.6702	10.0%
0.6201	9.1%
0.5496	4.1%
0.5757	4.8%
0.5892	5.4%
0.5284	4.1%
0.5897	5.3%
0.6129	8.7%
0.5871	6.2%
0.5419	4.1%
0.5616	5.1%
0.6164	9.4%
0.5697	5.4%
0.5949	5.2%
0.6666	0.0%

Appendix B - Hardness Test Results

Sample	Good Unit	Bad Unit	Sample	Good Unit	Bad Unit
1	102	107	16	101	109
2	107	102	17	102	107
3	107	101	18	102	109
4	105	107	19	105	103
5	106	103	20	103	107
6	106	106	21	104	103
7	103	101	22	106	104
8	101	102	23	103	103
9	106	107	24	108	104
10	108	105	25	103	106
11	105	106	26	107	108
12	103	106	27	104	104
13	107	109	28	102	103
14	106	106	29	103	107
15	104	106	30	105	104

Appendix C - Other Root Cause Validation

10.2 Other Root Cause Validation

10.2.1 Material: Big yoke gap

The Pairwise Pearson Correlation Method for Yoke Gap and Failed Adjust (FA) rejection (Figure 31) resulted in a P-Value of 0.321, which is higher than the set alpha level of 0.05, thus, the test result failed to reject the Null Hypothesis (H_o) and confirmed that the Yoke Gap does not have significant correlation and is not a valid root cause of Failed Adjust (FA) rejection.

Method						
Correlation by	0e	Pearson				
Number of rov	ws used	30				
p: pairwise Pe	arson corn	elation				
Correlation	ns					
	Yok	e				
	Tunne	el 🛛				
	Heigh	t				
Failed Adjust	-0.18	7				
airwise Pe	earson	Correlatio	ns			
Sample 1	Sample	2	N	Correlation	95% CI for p	P-Value
Failed Adjust	Yoke Tu	nnel Height	30	-0.187	(-0.513, 0.185)	0.321

Fig 31: Pairwise Pearson Correlation Method Result for Yoke Tunnel Height and Failed Adjust (FA) Rejection

10.2.2 Machine: Not Optimized Shim Welding Parameter

The Process Capability Shim Weld Strength (Figure 32) has a Ppk of 1.34, which is higher than the standard Ppk requirement of 1.33, thus, indicating that the set parameter for the shim welding process is optimized and not a valid root cause of Failed Adjust (FA) rejection.



Fig 32: Process Capability Result of Shim Weld Strength

10.2.3 Method: Lacking Reed Welding Criteria

The Control Plan of Model S (Figure 33) shows that all critical parameters of the Reed Welding process are already included on the SPC, thus, the lack of Reed Welding Criteria is not a valid root cause of Failed Adjust (FA) rejection.

								Me	thods					Valid Documents
Proces				Inspection	herns	Spec			Rat	dom 1	Sample		Respon	(Inspection Protocol.
Numbe	Process Name	Equipment / Tool	No.	Product	Process & Material	Class	Specification/ Tolerance	Equipment	•	d	Freq.	Method	Person	Working Instructions, OCAP)
_			_			_			_					
2	Reed Welding	Profile Projector, eSPC Falue	7	Reed Length, Tine Length, Tine Length, C Value, F Value, C Value, Food Parallelism Reed Parallelism	Reed dimension check	¢	texa intentio omitt	nally ed	Spea	0	2x per shift; every after machine mpair	Visual Dimensional	Operator	NEP-QAD PQC- W-387 KEP-QAD WHOO &SPC Dubbase KEP-QAD GP-01
2	Reed Welding	Pull Tester Pull Test Fisture	8	Reed Weld Strength	Puli Test	¢			Spos	0	2x per shift; every after machine repair	Visual Puli Test	Operator	KEP-QAD-PQC- Wi-287 KEP-QAD-Wi-003 eSPC Database KEP-QAD-GP-01

Fig 33: Control Plan of Model S

10.2.4 Measurement: Incorrect Configuration

The test configuration of Model S indicated on the Knowles Test Specification Database System matches with the correct part number for Model S as shown in Figure 34.

Cont	iguration List:									
Sear	ch Test Configuration									
Conf	guration Name:	Model	S Owne	er:			✓ Test Node:	-	× ''	%" is the wildcar
Test	System:	7	✓ Test I	Name:	[Create Date:	From	То	
ECO:			Devia	tion Number:			Creator:			
_										
No	Configuration Name C	wner	Test System	Test Mode	Deviation No.	Status	Creator	Time	Last Used	History
1	Model S 📕 🕴	EP	Fcaat	Final Test		Active	DeGuzman, Johannes Bruce	12/12/2022 7:39:59 PM	4/27/2024 10:24:55 PM	History
2	Model S 8	EP	Fcaat	Green Test		Active	DeGuzman, Johannes Bruce	12/12/2022 7:39:56 PM	4/29/2024 2:08:25 PM	History

Fig 34: Test Specification Database System Result

10.2.5 Environment: Temperature and Humidity Issue

A one (1) week data of production room temperature and humidity are gathered and plotted into a Time Series Plot. There is no abnormal spike observed for Room Temperature Time Series Plot (Figure 35) as well as for Room Humidity (Figure 36) and all data are within the specified limits. This confirms that there are no issues with room temperature and humidity and validated that these are not valid root causes of Failed Adjust (FA) rejection.



Fig 35: Time Series Plot of Production Room Temperature



Fig 36: Time Series Plot of Production Room Humidity

10.2.6 Material: Bad Yoke Tunnel Height

Regression analysis for Yoke Tunnel Height and Failed Adjust (FA) rejection (Figure 37) resulted in a P-Value of 0.321 which is higher than the set alpha level of 0.05, thus, the test result failed to reject the Null Hypothesis (H_o) and confirmed that the Yoke Tunnel Height is not a valid root cause of Failed Adjust (FA) rejection.

Coefficients						
Term	Coef	SE Coef	T-Value	P-Value	VIF	
Constant	1.19	1.07	1.12	0.274		
Yoke Tunnel Height	-0.908	0.899	-1.01	0.321	1.00	
S R-sq 0.0584966 3.51%	R-sq(a 0.0	dj) R-sq(j 7% (pred) 0.00%			
<u>S R-sq</u> 0.0584966 3.51%	R-sq(a 0.0	dj) R-sq(j 7% (pred) 0.00%			
S R-sq 0.0584966 3.51% Analysis of Varia	R-sq(a 0.0	dj) R-sq(7% (pred) 0.00%			
S R-sq 0.0584966 3.51% Analysis of Varia Source	R-sq(a 0.0 nce DF	dj) R-sq(j 7% (Adj SS	pred) 0.00% Adj MS	F-Value	P-Value	
S R-sq 0.0584966 3.51% Analysis of Varia Source Regression	R-sq(a 0.0 nce DF 1	dj) R-sq(j 7% (Adj SS 0.003487	pred) 0.00% Adj MS 0.003487	F-Value	P-Value 0.321	<u>.</u>
S R-sq 0.0584966 3.51% Analysis of Varia Source Regression Yoke Tunnel Height	<u>R-sq(a</u> 0.0 nce DF 1 1	dj) R-sq(j 7% (Adj SS 0.003487 0.003487	pred) 0.00% Adj MS 0.003487 0.003487	F-Value 1.02 1.02	P-Value 0.32 0.32	<u>.</u>
S R-sq 0.0584966 3.51% Analysis of Varia Source Regression Yoke Tunnel Height Error	<u>R-sq(a</u> 0.0 nce DF 1 1 28	dj) R-sq() 7% (Adj SS 0.003487 0.003487 0.003487 0.003812	Adj MS 0.003487 0.003487 0.003487 0.003422	F-Value 1.02 1.02	P-Value 0.321	<u>.</u>

Fig 37: Regression Analysis of Yoke Tunnel Height and Failed Adjust (FA) Rejection

10.2.7 Man: New and Certified Operators

It is confirmed that all operators running in Model S are trained and certified based on the Operators Training and Certification Card (Figure 38), thus, the uncertified operator is not a valid root cause of Failed Adjust (FA) rejection.

Knowl	es Skills Ce	rtification Ca	rd		4 € knowl	es Skills	Certification	Card		4 € knowl	es Skills C	ertification Ca	rd	
BADGE	NAME	n	elyn		BADGE	NAME		elle Ann		BADGE #	NAME	an	ice	
	POSITION	Operator	-			POSITION	Operator				POSITION	Operator		
PRODUCT LINE/	PROCESS/	EQUIPMENT	TYPE	VALID UNTIL	MODUCT UNI/	PROCESS	/ EQUIPMENT	THE	VALID UNTIL	MODUCT UNI/	PROCESS	/ EQUIPMENT	THPE	VAUD UNTE
	LEAKTEST		195	August 2024		SOLDER TERMIN	A.	R	August 2024		D'AFHRAGM AT	ADS .	18	March 2024
	GA TRANK		REX	And Stat		SEAL TERMINAL		RIX	March 2024		DAPHRAGM AT	IACH & SEAL DR ROO	RD	August 2024
Model S	AVE TOT CAME	NC AND IMATING	REX	Gentember 3034	Model S	-		-		Model S	DIA SEALING & A	PRYDROME	RB	August 2024
	INSULATION TEST	no vez zanatne	FLEX	March 2024							DUAPHRIAGM SEA	uns	N.D.	August 2024
			_			-		-		-	-		-	

Fig 38: Model S Operator's Certification Card

10.2.9 Method: Statistical Process Control Not Followed

The SPC record below (Figure 39) shows that the SPC for Model S is properly executed therefore it is not a valid root cause of Failed Adjust (FA) rejection.

SPC Setup	Lot		Process Equipment	_	Resource		_	
Aodel S _Reed Weid_C Value				~			~	
hocess Recipe	SPC Matrix	Context	SPC Result	_	SPC Fail	are Action	-	
				~			~	
:DO Name			Start Date	-	End Date		100	
Clear All Search			02/01/2023 12:00 AM		01/14/20	23 12 00 AM		
Clear All Search]		020112023 12:00 AM		01/1420	23 12 09 AM		
Clear All Search earch Results PC Setup Lot	,	Process Equipment	Resource	Process Rec	01/1420	SPC Matrix Conte	ext SPC (dest
Clear All Search earch Results PC Setup Lot kodel S Read Wald, CP		Process Equipment	Resource	Process Rec	ipe	SPC Matrix Conte	at SPC I	Rest
Clear All Search earch Results PC Setup Lot kodel S Reed Weld (2) kodel S Reed Weld (2)		Process Equipment	Resource	Process Rec	ipe	SPC Matrix Conte	xt SPC I PASS PASS	Rest
Clear AB Search earch Results PC Setup Eot todel S Reed Weld, 02 t		Process Equipment	Resource	Process Rec	ipe	SPC Matrix Conte	ext SPC I PASS PASS PASS	Resu
Clear All Search earch Results PC Setup Lot bodel S Reed Well, (2) bodel S Reed Well, (3) b		Process Equipment	Resource	Process Rec	ipe	SPC Matrix Conte	ext SPC (PASS PASS PASS PASS	Resu
Clear All Search earch Results PC Setup Color Addel 5 Reed Well, (2) Addel 5 Reed Well, (2) Addel 5 Reed Well, (2)		Process Equipment	Resource	Process Rec	ipe	SPC Matrix Conte	RE SPC I PASS PASS PASS PASS PASS PASS	Resu

Fig 39: SPC Record for Model S

10.2.10 Machine: Reed Welding Fixture Issue

The Reed welding fixture machine passed the buy-off requirement of Knowles, as shown in Figure 40, with a Ppk of above 1.33, thus, there is no issue on the reed welding fixture, and confirmed that it is not a valid root cause of Failed Adjust (FA) rejection.



Fig 40: Machine Buy-off Result of Reed Welding Fixture

10.2.11 Man: Bad Judgement

The operators in Model S passed MSA GR&R (Figure 41) with a 2.84% Gage R&R which is lower than the set standard of 10% and an NDC of 49 which is higher than the set standard of 5, thus, the operator can properly judge the defects and not a valid root cause of Failed Adjust (FA) rejection.

Gage Evaluati	on		
		Study Var	%Study Var
Source	StdDev (SD)	(6 × SD)	(%SV)
Total Gage R&R	0.02948	0.17686	2.84
Repeatability	0.02948	0.17686	2.84
Reproducibility	0.00000	0.00000	0.00
OP ID	0.00000	0.00000	0.00
Part-To-Part	1.03769	6.22616	99.96
Total Variation	1.03811	6.22867	100.00
Number of Distin	ct Categories =	49	

Fig 41: Gage R&R Result of Operator in Reed Welding Process



Fig 42: Gage R&R (ANOVA) Report for Unit Width

10.2.12 Material: Diaphragm Forming Issue

The Paired T-Test (Figure 43) resulted in a P-Value of 0.692, which is higher than the set alpha level of 0.05, thus, the test result failed to reject the Null Hypothesis (H_o) and confirmed that the Diaphragm Height does not change after re-forming and not a valid root cause of Failed Adjust (FA) rejection.

	est and	d CI: Be	fore Foi	rming, After Formir
Descriptive	Statis	tics		
Sample	Ν	Mean	StDev	SE Mean
Before Formin	g 29	0.106204	0.002970	0.000552
After Forming	29	0.106166	0.002998	0.000557
0.000038 0 μ_difference: μ	0.000512	0.000095 mean of (Bet	(-0.0001 ore Forming	57, 0.000233) • After Forming)
0.000038 0 μ_difference: μ	0.000512	0.000095 mean of (Bef	(-0.0001 ore Forming	57, 0.000233) After Forming)
0.000038 0 μ_difference: p Test Null hypothes	0.000512	0.000095 mean of (Bet	(-0.0001 fore Forming -	After Forming)
0.000038 C μ_difference: μ Test Null hypothesi Alternative hyp	0.000512 population is pothesis	0.000095 mean of (Bet H ₀ : μ_diffe H ₁ : μ_diffe	(-0.0001 fore Forming - rence = 0 rence ≠ 0	57, 0.000233) • After Forming)
0.000038 C μ_difference: μ Test Null hypothes Alternative hyp T-Value P	0.000512 hopulation is pothesis -Value	0.000095 mean of (Bef H ₀ : μ_diffe H ₁ : μ_diffe	(-0.0001 fore Forming - rence = 0 rence ≠ 0	57, 0.000233) • After Forming)

Fig 43: Paired T-Test Result of Diaphragm Height